

**NOTE:**  
The V500 ECU must be configure for Stepper Motor Idle Speed Control.

Stepper Motor Connector  
Male Pin View

